



David O'Neill - C.M.S.

CONDITION AND VALUATION SURVEY REPORT

This report is prepared subject to the terms and conditions on the last page.



M/V "Babble On"



Material:

U/K

NORTHWEST MARINE SURVEY



David O'Neill - C.M.S.

CONDITION AND VALUATION SURVEY REPORT

This report is prepared subject to the terms and conditions on the last page.

Vessel Name:	: M/V "Babble On"		Date of Survey:	10/7/2025								
Hauled:	No		Afloat:	Yes,								
Location:	N/A		Official No.:	1151325								
Home Port:	Portland, Oregon		Hull No.:	WELC2957B787								
Requested by												
Email Addres	s:			Phone:								
Owner:	Mallanaft Marina Oa	D!	Welleroft Marine Corn	MadalWass	4007							
Builder: Vessel Type:	Wellcraft Marine Co Twin Inboard Diese		Wellcraft Marine Corp.	Model Year: Displacement:	1987							
LOA:		L: U/K	Beam: 14'6"	Displacement. Draft:	3' 1"							
20/11	10 1	L. <u>0/10</u>	BCaiii. <u>1+0</u>		<u> </u>							
HIN:												
				16 94								
	MEI	020		7								
			9 1 8 7 8	7.1								
				1								
CONCTRUCTION												
		CONICED	CONSTRUCTION									
		CONSTR	<u>UCTION</u>									
Hull:	Solid and cored FI		<u>UCTION</u>									
-	Solid and cored Fi	RP laminates	UCTION									
-		RP laminates	<u>UCTION</u>									
-		RP laminates										
Superstructu	Ire: Solid and cored FF	RP laminates RP laminates ENGI	NES	Indicated Hou	ro: 1200/1191							
Superstructu	Solid and cored FF	RP laminates RP laminates	NES TA HP: 375	_Indicated Hou	rs: <u>1209/1181</u>							
Superstructure Fuel: Cooling:	Diesel Make:	RP laminates RP laminates ENGI	NES TA_HP: 375 Exhaust: Wet,	through hull	rs: <u>1209/1181</u>							
Superstructure Fuel: Cooling: Ventilation:	Solid and cored FF	RP laminates RP laminates ENGI 2-Caterpillar 3208	NES TA HP: 375	through hull	rs: <u>1209/1181</u>							
Superstructure Fuel: Cooling: Ventilation:	Diesel Make: Closed cooling Forced and Natural	RP laminates RP laminates ENGI 2-Caterpillar 3208	NES TA_HP: 375 Exhaust: Wet,	through hull	rs: <u>1209/1181</u>							
Superstructure Fuel: Cooling: Ventilation:	Diesel Make: Closed cooling Forced and Natural	RP laminates RP laminates ENGI 2-Caterpillar 3208	NES TA HP: 375 Exhaust: Wet, Fuel Filters: 2	through hull	rs: <u>1209/1181</u>							
Fuel: Cooling: Ventilation: Serial No.:	Diesel Make: Closed cooling Forced and Natural Port: 01Z06510 Starbo	RP laminates RP laminates ENGI 2-Caterpillar 3208 pard: 01Z07708	NES TA HP: 375 Exhaust: Wet, Fuel Filters: 2	through hull Racor 900MA	rs: <u>1209/1181</u>							
Superstructure Fuel: Cooling: Ventilation:	Diesel Make: Closed cooling Forced and Natural	RP laminates RP laminates ENGI 2-Caterpillar 3208 pard: 01Z07708	NES TA HP: 375 Exhaust: Wet, Fuel Filters: 2	through hull	rs: <u>1209/1181</u>							

Stuffing Box: Yes

Bearings: no

Vessel Survey Report Page No.: 3 of 10

EXTERIOR EQUIPMENT

Windlass:		2-volt Maxwell-Nil	lson single	direction					
		nnett 12-volt hydraulic Bow Thruster: none							
Other:					n isinglass enclosure, 12-				
	controlled spotlight, Dual 12-volt windshield wipers, Rail mounted fender holders, Custom								
	<u>LE</u>	D courtesy lights	s, Docking li	ghts, 6" Brass bell					
			<u>THRU</u>	<u>-HULL FITTINGS:</u>	<u>.</u> <u>-</u>				
Material:	<u>Br</u>	onze		Valves: 1/4 1	turn ball				
				BILGE:					
Water:	2" forwa	rd and aft	Oil: for	ward Fuel :	none Debris	ves			
					gh water alarm and coun				
			WΔ	ASTE SYSTEM					
				tore oronem					
Techma Fro	eshwater	electric flush toil	et. 35 galloi	n polypropylene holo	ding tank, 12 volt macera	tor			
			- i, J	. резурторують по	<u>g</u>				
			<u> </u>	UEL TANKS					
Quantity:	2		Canacity:	436 gallons	Material: Alun	ninum			
Shut-off:		Vents:		Secured:		ed: yes			
	, , , ,)			- <u> </u>			
			<u>W</u>	ATER TANKS					
				400 !!					
Quantity:			Capacity:	100 gallons	Material: Polyp	ropylene			
Shut-Off:	taucets		Vents:	yes	Secured: yes				
			WA	ATER SYSTEM					
	yes	Manua		Pressure:					
	no	Manual		Pressure:					
Water Hea	ter: <u>115</u>	5-volt	Si	ze: 11-gallons	Pressure Relief: _	50 psi			
			ELEC	TRICAL SYSTEM					
Dottories (9 \/al4a~:	n. (4) Craum 24	10 volt o = =	alad (2) Craum 24 -	colod lood asid. Oraciis O	71 and Anid 10			
Batteries & Main Disco	-				ealed lead acid, Group 2				
Main Disco DC Circ. P		Rotary x 4		verter: Freedom 2		/es			
AC Circ. P					Insulated Copper	Dual line 204			
Battery Ch				iring: Insulated cop	Shore Power: 30 A 50ft. shore power of	Dual line 30A			
Dailery Cr Δuxiliary (•	Xantrex True		Other: (2) S/N: K860856244	Hours: 688	orus			

Vessel Survey Report Page No.: 4 of 10

FIRE EXTINGUISHERS

Hand Units: 4-Type B:C Dry chemical

Date Tested: 1996 **Condition:** charged

Automatic System: Fireboy FE-241 with discharge tester

Date Tested: 1987 Capacity: U/K

GALLEY EQUIPMENT

Stove: Seaward Princess electric **Fuel:** Alcohol

Other: Dual tub stainless steel sink, Litton microwave, Black and decker spacemaker, Nutone blender

Tanks: None Shut-off Valve: - Secured: -

Propane Shut-Off Valve: — Ice Box: none Reefer: none

Refrigeration Equipment: Norcold AC/DC

NAVIGATIONAL EQUIPMENT AND ELECTRONICS

Compasses: Richie 5" Powerdamp Auto Pilot: Raymarine ST6002

Depth Sounder: Raymarine C-120

Radios: Standard Horizon Eclipse + VHF, Icom ICM45 VHF

AIS:Raymarine C-120GPS:Raymarine C-120Radar:Raymarine C-120Plotter:Raymarine C-120

Knotmeter: Raymarine C-120, Raymarine ST60 **Log:** none

Other: Raymarine wind meter, Engine synchronizer, Rudder angle indicator

GROUND TACKLE

Anchors: Galvanized Danforth Navy Type 35 lb.

Chain: 3/8" galvanized Line: 5/8" Nylon Rode

ENTERTAINMENT EQUIPMENT

Homeworx digital converter
JVC 32" TV on mount
Magnavox Blueray player
JVC AM/FM Receiver

JVC subwoofer, amplifier and 4-6" speakers

ADDITIONAL EQUIPMENT

4- Perko sea strainers

Wellcraft sea water, interior and exterior temperature monitors

PYI/PSS shaft seals

Water and waste level lights

Multiple Type 2 adult PFDs

Groco ARG-750 sea strainer

Handheld horn

Olin flare kit (expired)

First aid kit

Vessel Survey Report Page No.: 5 of 10

VALUATIONS

Vessel's Estimated Fair Market Value:\$ 35,000.00Replacement Value with Like Used Vessel:\$ 44,000.00Replacement Value with Like New Vessel:\$ 870,000.00


CONDITION: Good

The Fair Market Value is the amount in US dollars a willing, informed buyer would pay a willing, well informed seller in an open market, neither being compelled to buy or sell, given a reasonable amount of time to sell. It is the value of this vessel as is, where it is. Values are based upon the following: actual selling prices of similar vessels from the NWMS database, various pricing guides, comparables research and the opinions of other marine industry professionals.

The Replacement Value with Like Used is the likely value of this vessel with all significant Findings And Recommendations resolved in a satisfactory manner.

The Replacement Value with Like New is the estimated cost to replace with a similar, new vessel. In many cases, a particular model is no longer in production and the estimation is based upon similar new vessels currently available.

JD POWER BOOK VALUE



Vessel Survey Report Page No.: 6 of 10

FINDINGS AND RECOMMENDATIONS (*Immediate Attention is Required)

*A. Line 2 shore power cord end and inlet are burnt.

Recommendation: Replace the shore power cord and inlet.

*B. The center deck hatch tensioner is seized and cannot be opened.

Recommendation: Prove this hatch opens and closes.

*C. The red and green navigation lights are inoperable

Recommendation: Prove the vessel has operable navigation lights (USCG Requirement)

*D. The dry chemical fire extinguishers are past the end of their lifespan. The automatic unit discharge light is not illuminated.

Recommendation: Install 3 new fire extinguishers located in the salon, and cockpit.

Mount the units horizontally if possible in readily accessible areas. Have the bilge unit inspected as well to ensure it is operable.

*E. The vessel lacks CO and smoke detectors.

Recommendation: Install a CO/smoke detecting unit in the salon and forward cabin

*F. The courtesy light wires at the cabin entry step are pulled tight.

Recommendation: The courtesy light wire needs to be extended.

*G. The forward bilge pump is inoperable

Recommendation: Make the necessary repairs to prove the pump is operable automatically and manually.

*H. The PYI shaft seals are past due for the rider seal and boot replacement.

Recommendation: Have the seals attended by a qualified marine repair facility.

*I. The port side aft exterior exhaust cover through hull bolts are seeping water into the bilge.

Recommendation: Repair/rebed the leaking through bolts.

*J The starboard exhaust is leaking in the interior at the through hull flange.

Recommendation: Repair the leak and prove the exhaust system is leak free.

*K. The distress signal kit is expired.

Recommendation: Install a valid aerial distress signal kit. (USCG requirement)

*The resolution of the above asterisk items is considered essential for the continued safe use or operation of this vessel.

GENERAL NOTES:

- 1. A mechanical inspection nor a sea trial was performed by this surveyor.
- 2. The intended use of this vessel is the intercoastal waterways of the Pacific Northwest and California.
- 3. The owner was present for the inspection

REPORT

This 1987 Wellcraft 43 Portofino was attended on October 7, 2025, in Portland. Oregon. The vessel was surveyed while in the water at vessel to be in good condition structurally. Cosmetically, the interior is in original condition. The superstructure exterior gelcoat is dirty but in good condition. I believe this vessel will be a good insurance risk after the immediate items, indicated with (*) are attended. All items are in good working order unless otherwise noted.

NORTHWEST MARINE SURVEY Vessel Survey Report

Page No.: 7 of 10

SURVEY LIMITATIONS

This report is valid at the time of inspection and is not a warranty of the condition of the vessel or associated equipment. This report does not represent a complete record of all information exchanged verbally between the surveyor and client. The surveyor cannot be held responsible for any misstatement. This report is provided for the exclusive and confidential use of the client and his designated agents. Use of this report to gain financing, insurance, or to close in the purchase of the vessel contained in this report, shall thereby stand as acceptance of the terms and conditions contained in these Survey Limitations. The mandatory standards promulgated by the United States Coast Guard (UCSG), under the authority of Title 46 United States Code (USC): Title 33 and 46, Code of Federal Regulations (CFR), and the voluntary standards and recommended practices developed by the American Boat and Yacht Council (ABYC), and the National Fire Protection Association (NFPA), have been used as guidelines in the conduct of this survey, but complete compliance with all such standards is not guaranteed. Findings reflect conditions observed at the time of the survey, and only deficiencies were noted.

The American Boat and Yacht Council "standards and recommendations" are defined by reference to "ABYC". These standards were developed in cooperative effort with the National Marine Manufacturers Association, to complement, the mandatory standards promulgated by the United States Coast Guard under the authority of the Federal Boat Safety Act of 1971. The ABYC Standards and Recommendations are voluntary but are highly recommended by this surveyor. The recommendations are based on the Regulations of the United States Coast Guard (USCG), as well as the voluntary standards and guidelines of the American Boat & Yacht Council (ABYC), and my opinion based on knowledge and experience.

This report is a statement of the surveyor's opinions of conditions aboard the vessel at the time of survey and is based on a visual inspection of accessible areas. There has been no destructive testing, nor any removal of bulkheads, fastened paneling, or any part of the vessel's structure or equipment.

Machinery will be visually inspected without disassembly, and tanks inspected only on visibly accessible surfaces and without opening fastened access ports. The rigging was visually inspected at deck level only. The rigging observations in this report do not constitute a rigging survey. If a rigging survey is desired, then a suitable rigging company should be contacted.

This report is valid at the time of inspection and is not a warranty of the condition of the vessel or associated equipment. This report does not represent a complete record of all information exchanged verbally between the surveyor and client.

The surveyor cannot be held responsible for any misstatement. This report is provided for the exclusive and confidential use of the client and his designated agents. During maintenance, modification, or repairs to the boat, and through the use of the boat, additional conditions will be discovered that were not evident at the time of survey. Discoveries of this nature are a normal aspect of boat ownership. There has been no water testing for leakage at deck hatches and fittings; leakage at these installations is common on new vessels and especially common on seasoned vessels. Interior spaces of any boat are subject to mildew and mold formation, which is hazardous to persons sensitive to these conditions. This hazard can be minimized with a routine of thorough cleaning and proper ventilation of all interior living and storage spaces on the vessel.

Testing the vessel in the water under load, if performed, shall be referred to with the generic term "Sea Trial". This term has no bearing on the wind or weather conditions, or body of water upon which the vessel was tested and provides no guarantee of how the vessel will perform under different conditions, upon different waterways and in different weather conditions. Acceptance and use of this report by the client acknowledges the client's understanding that the report has been composed of information that is believed to be true after reasonable investigation and inquiry but is not warranted to be so. The information was obtained without drilling, diving, ultrasonic, cleaning or opening up to expose parts or conditions ordinarily concealed. There were no tests for tightness or soundness conducted other than the conditions noted visually.

Acceptance and use of this report acknowledges the client's understanding that no determination of stability or structural strength has been made and no opinion is expressed.

NORTHWEST MARINE SURVEY Vessel Survey Report

Page No.: 8 of 10

SURVEY LIMITATIONS (continued):

Acceptance and use of this report acknowledges the client's understanding that Northwest Marine Survey does not accept any responsibility for damage or deterioration not found or discovered during the course of survey, nor for consequential damage, deterioration or loss due to any error or omission.

The client hereby undertakes to keep the Surveyor/Consultant and its employees, agents and subcontractors indemnified and to hold them harmless against all actions, proceedings, claims, demands or liabilities whatsoever or howsoever arising which may be brought against them or incurred or suffered by them, and against and in respect of all costs, loss, damages and expenses (including legal costs and expenses on a full indemnity basis) which the surveyor/consultant may suffer or incur (either directly or indirectly) in the course of the services under these conditions. Notwithstanding the above clause, in the event that the client proves that the loss, damage, delay or expense was caused by the negligence, gross negligence or willful default of the Surveyor/Consultant aforesaid, then, save where loss, damage, delay or expense has resulted from the Surveyor's/Consultant's personal act or omission committed with the intent to cause same or recklessly and with knowledge that such loss, damage, delay or expense would probably result, the Surveyor's/Consultant's liability for each incident or series of incidents giving rise to a claim or claims shall never exceed a sum calculated on the basis the Surveyor's/Consultant's charges.

SURVEYORS CERTIFICATION:

I certify to the best of my knowledge and belief: The statements of fact contained in this report are true and correct. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions, and are my personal, unbiased professional analyses, opinions, and conclusions. I have no present or prospective interest in the vessel that is the subject of this report, and I have no personal interest or bias with respect to the parties involved. My compensation is not contingent upon the reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value estimate, the attainment of a stipulated result, or the occurrence of a subsequent event. I have made a personal inspection of the vessel that is the subject of this report. This report should be considered as an entire document. No single section is meant to be used except as part of the whole. This report is submitted without prejudice and for the benefit of whom it may concern. This report does not constitute a warranty, either expressed, or implied, nor does it warrant the future condition of the vessel. It is a statement of the condition of the vessel at the time of survey.

David O'Neill Marine Surveyor

Member: ACMS

Association of Certified Marine Surveyors

10/7/2025 Date



Vessel Survey Report Page No.: 9 of 10

ADDITIONAL PHOTOGRAPHS



Vessel Survey Report Page No.: 10 of 10

ADDITIONAL PHOTOGRAPHS



END OF THE REPORT