

EXTRA ITEMS:

ENGINE FUNCTIONALITY OR DAMAGE:

WAS NOT ABLE TO START ENGINE

RECENT WORK OR REPAIRS / EXTRA VESSEL PARTS:

SAIL CONDITION (SAILBOATS ONLY):

TRAILER NOTES:

Not Roadworthy maybe RUSTED

NOTES:

Boat is located in front of our cottage at  
2408 AINEHURST TRAIL TRAVERSE AIN MILWAUKEE