

EXTRA ITEMS:

ENGINE FUNCTIONALITY OR DAMAGE:

Lower housing of engine is cracked from hitting a rock while skiing. Was not able to find replacement parts for the '71 engine.

RECENT WORK OR REPAIRS / EXTRA VESSEL PARTS:

SAIL CONDITION (SAILBOATS ONLY):

TRAILER NOTES:

Trailer has not moved in 3 years. Was in good working condition when last used. Trailer should be inspected before moving.

NOTES: