

-----

Invoice #: 81279 Work Order #: 39683


Invoice Date: 04/30/21


Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:





ID	Description	Quantity	Price UM	Total
----	-------------	----------	----------	-------

Services

LBR1 LABOR 312.50

Comment: 1. Inspected port engine for no start. Tested solenoid. Found bad starter. Removed and replaced starter with reman Chrysler starter. Test ran, OK.

Total Services: 312.50

Parts

CP REMAN CHRYSLER STARTER 1.00 @ 292.31 EA 292.31

Total Parts: 292.31

Total: 604.81 Tax: 17.54 Grand Total: 622.35




Invoice #: 81154 Work Order #: 39670 Invoice Date: 04/15/21

Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:



ID	Description	Quantity	Price UM	Total
Services				
LBR1 Comment: 1.	LABOR Jump started batteries (stbd engine	e) at launch at	gas dock	62.50
			Total Services:	62.50
			Total: Tax: Grand Total:	62.50 0.00 62.50



------

Invoice #: 79527 Work Order #: 38307 Invoice Date: 09/30/20

Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:

ID Description Quantity Price UM Total

Services

LABOR 180.00

Comment: 1. Inspect engine for poor running. Voltage good, 13.7V. Found ignition module

bad. Getting 200 degrees+ and resin dripping out of module. Advised.

LBR1 LABOR 180.00

Comment: 2. Ordered new module. Installed and tested. Boat runs great.

Total Services: 360.00

Parts

CP IGNITION SPARK MODULE 1.00 @ 195.38 EA 195.38

Total Parts: 195.38

Total: 555.38 Tax: 11.72 Grand Total: 567.10




79530 Invoice #: Work Order #: 37216 Invoice Date: 09/30/20

Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:



Description Quantity Price UM Total

Services

-----

LBR1 LABOR 1,680.00

Comment: 1. Remove and reinstall stbd engine assembly. Align stbd engine after reinstallation.

LBR1 LABOR 2,280.00

Comment: 2. Disassemble marinized components on engine. Flow test exhaust manifolds. Advise

on condition (found both exhaust manifolds cracked). Assemble all marinized

components onto Jasper Remanufactured long blocks. Bench run engine.

Note: Removed marinized components will be inspected after disassembly and

replacement suggested as required.

LBR1 LABOR 240.00

Comment: 3. Disassembled both exhaust assemblies. Reassembled elbows and end caps on new

manifolds.

LBR1 LABOR 300.00

Comment: 4. Change spark plugs in port engine. Tune up engine.

LABOR 240.00

Comment: 5. Lake test and adjust.

Total Services: 4,740.00

Parts

Jasper 5.9L Chrysler marine 1.00 @ 3,456.00 EA 3,456.00 Comment: long block assemblies w 2-yr Warranty

СP Core charge (damaged block) 1.00 @ 300.00 EA 300.00

CP Oil pan assembly 1.00 @ 175.00 EA 175.00

CP Tune up materials, belts, 1.00 @ 350.00 EA 350.00 Comment: fluids, hoses, fittings, etc.

Chrysler Exhaust Manifolds 2.00 @ 321 69 EA CP 643 38

CP Transmission Flex Plate 1.00 @ 296.92 EA 296.92



Invoice #: 79530 Work Order #: 37216 Invoice Date: 09/30/20

Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:

ID Description Quantity Price UM Total

Total Parts: 5,221.30

Total: 9,961.30 Tax: 313.28 Grand Total: 10,274.58



Invoice #: 79015 Work Order #: 36823 Invoice Date: 08/25/20

Final Quote by: JES

Boat Name:

Boat Year/Make: 1977 32 Egg Harbor

Boat Model: Hull Number:

ID Description Quantity Price UM Total

Services

------

LBR1 LABOR 330.00

Comment: 1. Inspect engines. Found hole in oil pan on stbd engine from failed connecting rods. Perform compression test on port engine. Port engine did start and run but sounds weak. Found low compression (70-80lbs) on port inboard bank and oil-fouled spark plugs.. Suggest replacing both port and stbd engine long blocks. Estimate to replace engines to follow.

Total Services: 330.00


Parts

\_\_\_\_\_\_

CP Shop supplies 1.00 @ 10.00 EA 10.00

> Total Parts: 10.00

Total: 340.00 Tax: 0.60 0.60 Grand Total: 340.60



## Paid Invoice

Invoice Number: 1706740 Invoice Date/Time: 06/30/22 12:00 PM





Item	Price	Qty	Total
REMOVE TRANS			
Removed transmission to access flywheel to replace ring gear. Found severely decaye owner and stopped repairs.	d stringers. Advis	ed	
Labor	\$140.00	6	\$840.00
Payment Allocation - 8/10/2022 (1826804)	(\$840.00)	1	(\$840.00)
Labor Parts Charges REMOVE TRANS Total			\$840.00 \$0.00 \$0.00 \$840.00
Subtotal			\$840.00
Total			\$840.00
Paid			(\$840.00)
Balance			\$0.00

### **Notice**

All accounts must be paid in full before launch. Terms are Net 30. Unpaid balances are subject to 2% finance charge per month.



## Paid Invoice

Invoice Number: 1655056 Invoice Date/Time: 06/07/22 09:26 AM




Vessel - 32 Egg Harbor

Item	Price	Qty	Total
Port Engine			
Labor	\$125.00	5.5	\$687.50
Owner reports hard start. Inspected and found dead batteries. Charger was off. Turned charger on and left. Returned and tested batteries (bad). Removed and replaced batteries. Started both engines. Port runs great but starter is bad. Removed and replaced starter with reman. Filed teeth on flywheel that were damaged by starter. Tested, OK.			
27M-XHD Interstate Cranking Battery use \$16 core	\$159.39	2	\$318.78
Miscellaneous/Ship Store Special Order	\$112.50	1	\$112.50
REMAN STARTER - ADEMAS			
Payment - Amex - 6/14/2022	(\$1,144.66)	1	(\$1,144.66)
Labor Parts Charges Port Engine Total			\$687.50 \$431.28 \$0.00 \$1,118.78
Subtotal			\$1,118.78
Тах			\$25.88
Total			\$1,144.66
Paid			(\$1,144.66)
Balance			\$0.00

### **Notice**

All accounts must be paid in full before launch. Terms are Net 30. Unpaid balances are subject to 2% finance charge per month.



# Paid Invoice

Invoice Number: 1556947 Invoice Date/Time: 03/31/22 12:00 PM



**Vessel** - 32 Egg Harbor

item	Price	Qty	Total
Stbd Gel			
Labor	\$125.00	12	\$1,500.00
Gelcoat repair 12' long gouge on starboard hullside.			
Materials	\$150.00	1	\$150.00
Labor Parts Charges Stbd Gel Total			\$1,500.00 \$150.00 \$0.00 \$1,650.00
Cabin Top			
Labor	\$125.00	9	\$1,125.00
Repair starboard AFT underside corner of cabin top. Repaint repair area white. Reinstall teak tr	im.		
Materials	\$110.00	1	\$110.00
Payment Allocation - 4/12/2022 (1560005)	(\$2,900.60)	1	(\$2,900.60)
Parts Charges Cabin Top Total			\$1,125.00 \$110.00 \$0.00 \$1,235.00
Subtotal			\$2,885.00
Tax			\$15.60
Total Paid			\$2,900.60
raiu			(\$2,900.60)
Balance			\$0.00