EVE MARINE SURVEYORS, INC. THOMAS M. EVE, Marine Surveyor

Email: evesurvey@aol.com Tax ID: 58-2105719

VESSEL SURVEY REPORT

Prepared For:

M/V "AGE MANAGEMENT"



Conditional and Valuation 42' Chris Craft Commander 422 Sport Fish Savannah, GA **July 1, 2022**

Purpose and Scope

At the request of surveyor did, on Friday July 1, 2022 proceed to Savannah, GA in order to survey the M/V "AGE MANAGEMENT". The purpose of this survey was to establish the condition and to establish an appraised fair market value for the aforementioned vessel as well as present comments with recommendations regarding specific items, equipment, or general sections of the vessel.

Please find enclosed the aforementioned survey, comments, and recommendations. These comments and recommendations have been presented to the vessel owner and/or master.

and for the account of To Whom It May Concern

M/V "AGE MANAGEMENT" CONDITION AND VALUE July 1, 2022

COMMENTS AND RECOMMENDATIONS

M/V "AGE MANAGEMENT"

Throughout the course of survey the undersigned noted the following exceptions requiring attention:

Examination of vessel's hull above waterline revealed same in apparent good order although gelcoat chalky.

Vessel's generator noted without a sound cover and existing pan found moderately to heavily rusted. Unit would not start at time of survey. Suspected starved for fuel.

Both port and starboard engines started quickly on a cold start. Starboard engine smoked excessively for a short time at time of start but settled out to normal after approximately 10 minutes. Forward and reverse gear engaged and operated normal.

Forward head shower drain hose found with a small hole requiring replacement of hose.

Sea strainer servicing forward AC unit found with associated hoses single clamped requiring double clamping. Generator's sea strainer noted with associated hoses single clamped requiring double clamping. AC sea cock noted with hose clamps moderately corroded requiring replacement hose clamps installed. Generator exhaust hose clamps noted moderately corroded requiring replacement hose clamps installed.

Engine room after bilge pump's automatic switch not functioning requiring replacement. Lazerette bilge pump not functioning requiring repair or replacement.

Vessel's horn not functioning requiring repair. Vessel's searchlight not functioning requiring repair. Vessel's port side running light not functioning requiring repair. Engine room's halon 1301 fire extinguisher requires inspection. Emergency flairs and flair pistol cartridges all expired requiring renewal. Forward AC unit found not cooling. Unit found in running condition requiring servicing.

All sea cocks throughout vessel found frozen or very stiff to operate. Upon next scheduled haul- out all seacocks to be serviced.

Date:		July 1, 2022		
File Number:		3046-121		
Purpose of Survey:		Condition and Appraisal		
Name of Vessel:	M/V "AGE MANAGEMEN T"	Home Savannah, GA		
Document Numbe	r:	934148		
Hull Number:	Hull Number:		2K687	
Length Over All:		42.2'		
Beam:		14.0'		
Depth:		7.8'		
Type of Vessel:		Sport Fish,	442 Commander	
Use:		Recreation		
Builder:		Chris Craft		
Address:		Sarasota, FL		
Year Built:		1987		
Survey was made at:				
While the vessel was:		Fully afloat, underway and ashore in slings		
Would this vessel be a good fire and marine risk?		Yes, see recommendations		
Owner's marine losses during the past five years:		None reported		

Fair Market \$	68,500.00	Replacem ent Value:	\$775,000.00	
HULL CONSTRUCT	ION AND DETA	AILS:		
Material:		Polyester	fiberglass reinforced resin	
Thickness of Hull: (A	pproximate):	1/2" to 1-1	1/2" to 1-1/4" thick layup	
Framing Size and Ma	aterial:	Molded fil	perglass	
Deck Beams, Size, and Material:		Molded fil	Molded fiberglass	
Decking:		Gelcoat o	Gelcoat over fiberglass	
Bulkheads Location and Material:		machiner	One collision, one forward and aft of machinery spaces. Bulkheads noted constructed of fiberglass sheathed plywood.	
Type of Bottom:	Hard chine with slight to moderate deadrise			
Keel:	Molded fiberglass			
Skeg:	None			
Type of Stem:	Raked molded fiberglass			

MANAGEMENT" CONDITION AND VALUE July 1, 2022

M/V "AGE

Type of Stern: Square transom				
Propellers:	Four	Four bladed bronze with a spare set		
Propeller Shafts:	2" diameter stainless steel			
Packing Glands:	Thre	eaded collar packing gland		
Bearings:	Cutla	Cutlass		
Struts:	Two	cast bronze struts		
Propeller Protection:	Keel and hull configuration			
Rudders:	Cast bronze spade rudders			
Flectrolysis Protection	on:	See comments		
, and the second		None		
Grounding Plate: None		None		
Trim Tabs:		Yes, 36 x 12 Stainless		
Through Hull Fittings:				
Below Waterline: All silicon bronze		All silicon bronze		
Bonded: Yes				

Above Waterline:	Stainless steel				
Bonded:	Yes				
Emergency Plugs:	None				
Condition of Bilges:	Excellent				
Electric Bilge Pumps:	1 x Rule 1500 forward, 1 x and lazerette	x Rule 1800 aft machinery spaces			
Float Switches:	Yes				
Manual Bilge Pumps:	None				
Date of Last Haul-out and	Date of Last Haul-out and Maintenance: 2013, December				
MAIN ENGINES:					
	Port	Stbd			
MAKE:	General Motors	General Motors			
MODEL:	6V71-TI 6V71-TI				
YEAR:	1986 1986				
SERIAL NUMBER:	6A453622 6A452949				
Last Overhaul:	Unavailable Unavailable				
Flame Arrestor:	Yes Yes				
Cooling System:	-				

		Heat exchanger	Heat exchanger	
Flex Fuel Line @ Pump:		Yes	Yes	
Fuel Shut-off Valves	:	In-line & Racor	In-line & Racor	
Approved Filters:		Racor	Racor	
Exhaust Lines:	6" diameter neoprene hose with fiberglass connections			
Condition of Bilges:	Good			
Engine Alarms:	Yes			
Type of Blowers:	None			
Oil Pollution Placard:	Yes			

FUEL TANKS:			
Fuel Type:	Diesel		
Number:	Three		
Capacity:	625 gallons to	tal	
Shape:	Rectangular		
Material:	Aluminum		
Condition:	Good		
Bonded:	Yes		
Vented:	Yes		
Secured:	Integrated		
	•		
Fill Lines:		2.0" diameter Neoprene	
Location:		Port deck	
Overflow run overboard:		Yes	

Shut-off valves	at tank:	Yes		
Accessibility:		Machinery spaces		
Condition of Fu Connections:	iel Lines and	Good		
			T	
Addition Fuel o	r Flammable C	arried Aboard:	None	
Approved Cont	ainers:	N/A		
FRESH WATE	R SYSTEM:			
Number:		One tank constructed of welded aluminum.		
Shape:		Rectangular		
Hot Water Heater:		1 x 10 gallon 110 electric, Bosch Pro TI in-line		
ELECTRICAL	SYSTEMS:			
		Ι		
Batteries:		2 x 8d's for mains and 1 x 12 volt for generator		
Battery Switch:		Yes		
Vapor Proof:		Yes		
Battery Installation:		Fiberglass boxes outboard engines and adjacent to generator		
AA/inim m. l	<u> </u>			
Wiring type: Heavy gauge multi strand copper				
	•			

Connections:		Swaged
Fuse Panels/Breaker boxes:		12 and 110 volt factory installed breaker boxes
Battery charger:		1 x professional Marine 35 amp battery charger
Converter:		N/A
Shore Power connection:		Yes with splitter and shore chord
Auxiliary Generator: on centerline in forw		nan model 8-MDKD diesel positioned ard portion of machinery space.

M/V "AGE MANAGEMENT" CONDITION AND VALUE July 1, 2022 GALLEY: Galley located to port and down forward of main salon. Area houses a 110 volt stand-up freezer/refrigerator, Galley Maid Countess three burner electric range, and a stainless steel sink with pressure water. **MARINE HEADS:** Location: One forward, port side Marine Head Type: 12 volt electric flush Marine Sanitation Device: Holding tank Shower: Yes FIRE EXTINGUISHING EQUIPMENT: 1 x Halon 1301 25 lb in machinery spaces fitted Built in system: with a heat activated release mechanism.

Portable extinguis	shers:		ssel fitted with two (2) #10 dry chemical fire inguishers.	
VESSEL / PERS	ONAL SAFETY:			
Personal Floatation	on Devices: None			
Type "I":				
Mara Oversila a sual F) a. da a.	NI.		
Man Overboard D	Device:	No	ne	
Life Raft: None				
Visual Distress Fl hand held flairs a		ied v	with a current distress flair kit containing three	
EPIRB:			None	
First Aid Kit:			1 x First aid kits	
GROUND TACK	LE & MOORING LI	INE	S:	
Anchors:	One 18 Fortress			
Anchor Lines:	chor Lines: Approximately 200' of 1/4" galvanized chain			
Windlass/Winches:		1 x	12 volt bow mounted anchor windlass	
Dock or Mooring Lines:		Ad	equate	
Fenders:		Ad	equate	

DECK FITTINGS:	
Vents:	Fuel, water and waste tanks vented
Cockpit Drains:	Aft cockpit
Railings:	Stainless steel tubing
Bimini or Awning:	Flybridge fitted with a bimini top and clear view front and side skirting. Note: Not installed at time of survey
Hatches:	Bowmar type gasketed foredeck hatch

PILOTING, NAVIGATION & ELECTRONICS:

Steering System: Addition Stations: Engine/Clutch Controls: Engine Gauges:

Knot Meter/Speed Log: Compass:Horn:Bell:

Running Lights: Port: Starboard: Stern:

Mast Head: Radios: VHF: Both Stbd & Port Antenna Wire leads broken

SSB: Radar GPS: Depth: Auto Pilot:

Binoculars: Searchlight: Clock: Barometer: Anemometer:

	1
!!	l
Hydraulic	
None	11
None	
Morse cable clutch and throttle	,11
	II
Factory installed	
Integrated in GPS unit	_ 11
1 x Danforth Constellation magnetic compass	
	_ 11
House mounted trumpet	
	11
1 x brass bell	
	l
Yes	
	11

Yes		
Yes		
Yes	.11.	
West Marine ICOM		
Model:		
VHF-680 IC-M55		
S/N:		
Unavailable		
None	. — . —	
Model:		
S/N:		
Garmin	. — . —	
Model:		
Integrated		
S/N:		
Garmin	. — . —	
Model:		
GPS map 740		
S/N:		
Unavailable		
Garmin	. — . —	

Model:			
Integrated			
S/N:			
Unavailable			
None			
Model:			
S/N:			
1 x pair	 		
1 x ACR with remote	11		
1 x brass			
1 x Brass			
None			
INTERIOR AMENITIES & OTHER	SYSTEMS:		
Cushions/Covers:	Fair condition		
Curtains:	Removed at time of survey		
Cabin Sole/Carpets:	Carpet and parquet wood		

All interior

air handlers

Two marine Air AC compressors with associated

Woodwork:

Air conditioning Systems:

Recreational Electronics:	Main salon noted fitted with a Sony DVD player, stereo and amp with remote speakers and a Panasonic TV. Master cabin fitted with a Magnavox TV/DVD.

The above report is hereby signed and rendered without bias or prejudice **To Whom It May Concern**.

Respectfully submitted on behalf of Thomas Eve, Marine Surveyor

Signed		

EVE MARINE SURVEYORS, INC. THOMAS M. EVE, Marine Surveyor 31 Richmond Drive, Savannah, GA 31406 Office: (912) 355-5911 Fax: (912) 355-5913 Website: www.marinesurveyor.com/ems/



Side Profile in Water



Stateroom 1



Salon Looking toward Stern



Salon Looking toward Bow





Galley 2






Stateroom Looking to Head



Engine Room



Stbd Side Bunk Room