

EXTRA ITEMS:

Hummingbird fish feeder

ENGINE FUNCTIONALITY OR DAMAGE:

- none all work + maint receipts
avail.

RECENT WORK OR REPAIRS / EXTRA VESSEL PARTS:

- driver side window (vent window) broken
- included picture to show

SAIL CONDITION (SAILBOATS ONLY):

TRAILER NOTES:

NOTES: